



LEARNING FROM INCIDENTS NEWSFLASH

BSP-NF-201357

TWC – AMDP17 – BSP Well Services Wireline

Sept 2013

Wireline crew hurt wrist in AMDP17

Target audience for this newsflash:

- Wells Community
- Menang Partners / Service Providers



What happened:

On the 22nd of September 2013 at 0400hrs, a wireline crew had rig down lubricators having suspended intervention activities on the well SWA-276L (AMDP-17). During pulling the lubricator away from the K-lift Crane, the IP lost his grip and lost his balance which caused him to fall down. Using both his hands to support him from falling to the floor, he put more weight on his right hand and thus hurting his wrist.

Why it happened:

Investigation is still on-going.

Suggested toolbox/safety meeting questions:

- What is the condition of your PPE before you start your job? Ok to proceed?
- What are Manual handling techniques? They include pulling and pushing as well, not just lifting only.
- What is routine activity? Are those things done routinely always safe?

Further information

For more details, please e-mail Rahim Kamis (TWC/11) on abd-rahim.kamis@shell.com
Fountain No. (TBA)

This document is made available for information only and on the condition that (i) it may not be relied upon by anyone, in the conduct of their own operations or otherwise; (ii) neither Brunei Shell Petroleum Company Sendirian Berhad (BSP) nor any other person or company concerned with furnishing information or data used herein (A) is liable for its accuracy or completeness, or for any recommendations or advice given in or any omission from this document, or for any consequences whatsoever resulting directly or indirectly from any use made of this document by any person, even if there was a failure to exercise reasonable care on the part of BSP or any other person or company as aforesaid; or (B) makes any claim, representation or warranty, express or implied, that acting in accordance with this document will produce any particular results with regard to the subject matter contained herein, or to satisfy the requirements of any applicable federal, state or local laws and regulations and (iii) nothing in this document constitutes technical advice. If such advice is required it should be sought from a qualified professional advisor.

The content of this document may (i) be based on, but not identical to facts relating to a third party incident about which BSP has become aware; (ii) contain recommendations that are one, but not necessarily the only way, of addressing incident learnings.