



LEARNING FROM INCIDENTS NEWSFLASH

BSP-NF-201361

BSP – Well Engineering & Well Services

Oct 2013

Step ladder blown off from platform

Target audience for this newsflash:

- TSW Community
- TSW Menang Partners / Service Providers

What happened:

On 12th October, 2013 at 0100 hours slickline crew were working on SWA-306 at AMDP 25 while drilling crew were engaged in setting a shallow plug for temporary abandonment of SWA-314 two slots away on the same platform. With a sudden squall hitting the platform, a double sided stepladder made of fibreglass weighing 11.8 kg used by the slickline crew for operating valves and BOP on the platform top deck, was blown away into the sea.

Why it happened:

The investigation of this incident is not yet complete.

Suggested toolbox/safety meeting questions:

- Are all equipments secured?
- Do we understand change management?
- Do we have due considerations for weather conditions and their impact on operations?

Further information:

Fountain: TBA

Contact: Maersk Completer

DSV-Completer@shell.com



This document is made available for information only and on the condition that (i) it may not be relied upon by anyone, in the conduct of their own operations or otherwise; (ii) neither Brunei Shell Petroleum Company Sendirian Berhad (BSP) nor any other person or company concerned with furnishing information or data used herein (A) is liable for its accuracy or completeness, or for any recommendations or advice given in or any omission from this document, or for any consequences whatsoever resulting directly or indirectly from any use made of this document by any person, even if there was a failure to exercise reasonable care on the part of BSP or any other person or company as aforesaid; or (B) makes any claim, representation or warranty, express or implied, that acting in accordance with this document will produce any particular results with regard to the subject matter contained herein, or to satisfy the requirements of any applicable federal, state or local laws and regulations and (iii) nothing in this document constitutes technical advice. If such advice is required it should be sought from a qualified professional advisor. The content of this document may (i) be based on, but not identical to facts relating to a third party incident about which BSP has become aware; (ii) contain recommendations that are one, but not necessarily the only way, of addressing incident learnings.