



LEARNING FROM INCIDENTS NEWSFLASH

BSP-NF-201358

| BSP – Well Engineering & Well Services

| Oct 2013


Aft Crane in contact with Derrick Windwall Panel

Target audience for this newsflash

- TSW Community
- TSW Menang Partners / Service Providers

What happened

On 5th October 2013 at 8:40 am, the Aft Crane was being banked close to the Derrick to land a crossover sub on the aft part of the catwalk machine when the boom tip made contact with the Derrick Wind-wall. This impact caused a hole on the thin corrugated sheet of the forward starboard panel of the windwall to be torn upwards. No damage to any other asset, no injuries to personnel and no dropped objects..



Why it happened

- Under investigation

Suggested toolbox/safety meeting questions

- Is it a blind or critical lift?
- Does the JSA mention requirement of a 'spotter' in addition to the banksman?

Further information

Fountain: TBC

Contact: Maersk Completer/ Manish Kumar Rig SWE

DSV-Completer@shell.com Manish.Kumar@shell.com

This document is made available for information only and on the condition that (i) it may not be relied upon by anyone, in the conduct of their own operations or otherwise; (ii) neither Brunei Shell Petroleum Company Sendirian Berhad (BSP) nor any other person or company concerned with furnishing information or data used herein (A) is liable for its accuracy or completeness, or for any recommendations or advice given in or any omission from this document, or for any consequences whatsoever resulting directly or indirectly from any use made of this document by any person, even if there was a failure to exercise reasonable care on the part of BSP or any other person or company as aforesaid; or (B) makes any claim, representation or warranty, express or implied, that acting in accordance with this document will produce any particular results with regard to the subject matter contained herein, or to satisfy the requirements of any applicable federal, state or local laws and regulations and (iii) nothing in this document constitutes technical advice. If such advice is required it should be sought from a qualified professional advisor.

The content of this document may (i) be based on, but not identical to facts relating to a third party incident about which BSP has become aware; (ii) contain recommendations that are one, but not necessarily the only way, of addressing incident learnings.